
Automation Devices, Inc.

AF05.03

MODEL 5300A INLINE FEEDER ASSEMBLY DRAWING



Model 5300A Parts List		
Part No.	Qty.	Description
1022	6	5/16-18 x 1_1/2" SHCS
1046	7	5/16-18 x 1" SHCS
1092	3	5/16-18 x 2_1/2" SHCS
5126	1	Cable Strap
5301	1	Base Casting
5302	1	Top Casting
5303A	2	Short Spring 15 Ply
5304A	4	Long Spring 15 Ply
5306A	24	Spring Spacer 3 Ply
5307	7	Spring Cover
5311	1	120 Volt Coil
5312	Opt.	240 Volt Coil
5313	1	Reaction Casting with Armature
5314	1	Right Side Plate
5315	1	Left Side Plate
5318	2	Threaded Spring Cover
5335	1	5/16-18 Square Nut
5336	1	Fiberglass Washer
5337	1	5/16" Flat Washer
5338	1	Spring Cover with Slot
5345	1	Slotted Spring 15 Ply
5346	10	#10-32 x 1/2" BSHS w/washer
6212	2	1/4-20 x 1_1/4" SHCS
6304	3	5/16-18 x 3" SHCS
7035	1	#10-32 x 1/2" SHCS
8626	1	#10-32 x 3/8" Ground Screw

7050 West Ridge Road • Fairview, PA 16415-2099 • Phone: 814-474-5561 • Fax: 814-474-2131 • www.autodev.com • sales@autodev.com