


Automation Devices, Inc.

MODEL 5100A INLINE FEEDER ASSEMBLY DRAWING



Model 5100A Parts List

Part Nmbr	Qty	Description	Part Nmbr	Qty	Description	Part Nmbr	Qty	Description
5101	1	Base Casting	5115	1	Left Side Plate	5135	1	#10-32 T-Nut
5102	1	Top Extrusion	5116	1	Armature	5136	1	Stainless Steel Washer
5103	2	Spring 5 Ply	5117	2	#10-32 X 3/4" SHCS	5137	1	3/16" Steel Collar
5105	1	Spring 7 Ply	5118	3	Tapped Spring Cover	5142	1	Threaded Double Spring Cover
5106	2	Spring Spacer	5119	2	#10-32 X 3/8" FHSCS	5143	1	Slotted Long Spring 5 Ply
5107	3	Spring Cover	5123	4	#10-32 X 5/8" Slotted Pan HMS	6104	2	#10-32 X 1/4" SHCS
5108	2	Ground Strap	5125	7	#10-32 X 3/8" Slotted Pan HMS	6108	2	#10-32 X 5/8" SHCS
5111	1	120 Volt Coil	5126	1	Cable Strap	7035	1	#10-32 X 1/2" SHCS
5112	Opt	240 Volt Coil	5127	2	Double Spring Cover	7541	2	#10-32 X 1" SHCS
5113	1	Coil Yoke Extrusion	5128	2	Threaded Double Spring Cover	8416	4	#10-32 X 3/8" SHCS
5114	1	Right Side Plate	5129	4	#8-32 X 1/4" Slotted Pan HMS	8626	1	#10-32 X 3/8" Ground Screw

AF02.01

Automation Devices, Inc.

7050 West Ridge Road
Fairview, PA 16415-2099

Phone: 814-474-5561

FAX: 814-474-2131 or 800-235-9382

Web Site: www.autodev.com E-mail: info@autodev.com