


Automation Devices, Inc.

MODEL 5300 INLINE FEEDER ASSEMBLY DRAWING

AF04.02



Model 5300 Parts List

Part No	Qty	Description	Part No	Qty	Description	Part No	Qty	Description
1021	6	5/16 -18 X 1 1/4" SHCS	5304C	3*	Spring 9 Ply	5314	1	Right Side Plate
1046	9	5/16 -18 X 1" SHCS	5304D	1*	Spring 7 Ply	5315	1	Left Side Plate
1091	3	5/16 -18 X 2 1/4" SHCS	5304E	1*	Spring 5 Ply	5316	1	Armature
5126	1	Cable Strap	5304F	1*	Long Spring 3 Ply	5318	2	Threaded Spring Cover
5301	1	Base Casting	5306A	24	Spring Spacer 3 Ply	6151	10	#10 Flat SAE Washer
5302	1	Top Casting	5307	6	Spring Cover	6212	2	1/4 -20 X 1 1/4" SHCS
5303	2	Short Spring 9 Ply	5311	1	120 Volt Coil	7035	11	#10-32 X 1/2" SHCS
5304A	1*	Long Spring 15 Ply	5312	Opt	240 Volt Coil	8626	1	#10-32 X 3/8" Ground Screw
5304B	2*	Spring 11 Ply	5313	1	Reaction Casting			

* Quantity required depends on tuning for various track weights and for operating frequency.

Automation Devices, Inc.

7050 West Ridge Road
Fairview, PA 16415-2099

Phone: 814-474-5561

FAX: 814-474-2131 or 800-235-9382

Web Site: www.autodev.com E-mail: info@autodev.com