


# Automation Devices, Inc.

## MODEL 3 BASE UNIT ASSEMBLY DRAWING



Parts List		
Part Number	Quantity	Description
0301	1	Base
0302	1	Top Plate
0303	3	Springs (.118 Dia.)
0304	*	Springs (.140 Dia.)
0305A	*	Springs (.148 Dia.)
0305B	*	Springs (.100 Dia.)
0306	6	Spacers
0307	6	Spring Clamp
0308	optional	Rubber Mount
0309	3	Rubber Mount
0311	1	120 Volt Coil
0312	optional	240 Volt Coil
0321	12	#8-32 x 1/2" SHCS
0324	1	Shell
0326	1	Cord Strain Relief
0334	1	Coil Washer
0335	1	Rubber Washer
0336	1	1/4"-28 x 1" SHCS
0343	1	Mounting Plate
0346	1	#10-32 x 1/2" FHSMS
0347	1	#10-32 x 3/8" SHSS
0348	4	Rubber Grommet
0349	1	1/8 x 3/8" Spring Pin
0579	3	#8-32 Full Hex Nut
8626	1	#10-32 x 3/8" Gnd Screw

\* Quantity required depends on tuning for various bowl weights and operating frequency.

### Automation Devices, Inc.

7050 West Ridge Road  
Fairview, PA 16415-2099

Phone: 814-474-5561

FAX: 814-474-2131 or 800-235-9382

Web Site: [www.autodev.com](http://www.autodev.com) E-mail: [info@autodev.com](mailto:info@autodev.com)